
## Scan. Order. Done. Details on page A1.





## **Slide Bolt Spring Snaps**

- Nonload-rated, not for lifting
  Models E. to H. have swivel eyes

Key	Snap Opening	Eye Inside Dia.	Overall Length	Item No.			
Zinc Die Cast, Nickel-Plated							
A	7/16 in	1/2 in	3 1/4 in	4GGJ2			
A	7∕16 in	5⁄8 in	3 % in	4GGJ3			
A	7∕16 in	3/4 in	3 ½ in	4GGJ4			
В	3/8 in	_	4 in	4FCG3			
В	7∕16 in	_	4 % in	4FCG4			
D	7∕16 in	1 in Strap Width	3 % in	4FCN1			
E	1/4 in	3/8 in	2 ½ in	4FCG6			
E E	5/16 in	½ in	3 in	4FCG7			
	3/8 in	5⁄8 in	3 ½ in	4FCG8			
E	3/8 in	3/4 in	3 ½ in	4FCG9			
E	3/8 in	7∕8 in	3 ¾ in	4FCJ6			
E	3/8 in	1 in	3 % in	4FCJ7			
E	3/8 in	7∕8 in	4 1/16 in	4FCJ8			
F	7∕16 in	3/4 in Strap Width	3 1/4 in	4GGL2			
G	5/16 in	1 in Strap Width	3 1/8 in	4FCL2			
Steel, Chrome-Plated							
B	7∕16 in	3/8 in	3 ¾ in	1RCB1			
E	7∕16 in	3/8 in	3 in	4PB86			
Iron Casting, Zinc-Plated							
В	5/16 in	_	4 in	4FCJ3			
В	7∕16 in	_	4 % in	4FCJ4			
С	5∕16 in	5∕16 in	2 % in	4GGJ5			

			_	
Key	Snap Opening	Eye Inside Dia.	Overall Length	Item No.
C	11/32 in	3% in	3 % in	4GGJ6
С	3/8 in	9/16 in	3 ½ in	4GGJ7
С	3/8 in	9/16 in	4 in	4GGJ8
C	%16 in	7⁄8 in	5 ½ in	4GGK1
C	9/16 in	1 in	6 in	4GGJ9
Iron Castin	g, Nickel-Pla	ted		
E	5/16 in	5/8 in	3 1/4 in	4FCJ9
Bronze				
В	7/16 in	_	4 ¾ in	4FCJ5
C	3/8 in	½ in	3 ½ in	4GGK2
C	3/8 in	9/16 in	4 in	4GGK3
Ě	1/4 in	7/16 in	3 in	4FCH1
E	7/16 in	3/8 in	3 in	4PB87
Ē	9/16 in	1 1/4 in	4 3/4 in	4FCH2
H	3/8 in	3/4 in	3 5/8 in	4GGL3
316 Stainle				
В	7/16 in		4 in	4FCG5
Ē	1/4 in	7/16 in	2 ½ in	4GGK4
Ē	5/16 in	1/2 in	3 1/8 in	4GGK5
Ē	3/8 in	5/8 in	3 7/16 in	4GGK6
Ē	3/8 in	3/4 in	3 5/8 in	4GGK7
Ē	½ in	1 5/16 in	4 3/4 in	4GGK8
Ē	½ in	1 7/16 in	4 7/8 in	4GGK9
	72 111	. , 10 111	. , 0 111	·Juito











## **Magnetic-Mount Hooks**


Key	Hook Height	Hook Base Width	D	Hook Finish	Working Load Limit	Item No.
A	2 ½ in	2 ½ in	4 1/4 in	Painted	15 lb	4HDY5
В	1 3/8 in	1 3/8 in	1 5/8 in	Unfinished	4 lb	4HDZ5
С	1 1/4 in	1 1/8 in	1/4 in	Chrome	45 lb	3DXY2
D	1 in	1 % in	1/4 in	Chrome	40 lb	3DXY3
E	1 ¾ in	_	1/4 in	Chrome	20 lb	6YA67
F	1 in	2 in	1 in	Polished	20 lb	35HV66














G.





## **Braces and Reinforcement Hardware**

Key	L	w	Holes per Leaf	ltem No.	Pkg. Qty.
	Corner B	races			,.
Zinc					
A	3/4 in	½ in	1	1WDD4	1
A	1 in	½ in	1	4PB60	1
A	1 ½ in	½ in	2	4PB61	1
A	2 in	5⁄8 in	2	4PB62	1
A	2 in	2 11/16 in	2 2	1WDD1	1
A	2 ½ in	5⁄8 in	2	1WDD5	1
A	3 in	3/4 in	2	4PB63	1
A	3 ½ in	3/4 in	2 2	1WDD6	1
A	3 in	3 in		1WDD2	1
A	4 in	7⁄8 in	2 2	4PB64	1
A	4 in	4 in		1WDD3	1
A	5 in	1 in	3	4PB65	1
A	6 in	1 3/32 in	3	1WDD7	1
A	8 in	1 3/32 in	3	4PB66	1
A	10 in	1 1/4 in	4	1WDD8	1
Galvar					
A	1 in	½ in	1	1WDD9	2
A	1 ½ in	½ in	2	1WDE1	2
A	2 in	5⁄8 in	1	1WDE2	2
A	2 ½ in	19⁄32 in	2	1WDE3	2 2 2
A	3 in	<sup>23</sup> / <sub>32</sub> in	2 2	1WDE4	2
A	4 in	7⁄8 in	2	1WDE5	2
A	5 in	1 in	3	1WDE6	1
A	6 in	1 3/32 in	3	1WDE7	1
Α	10 in	1 1/4 in	4	1WDE9	1
Brass					
Α	1 in	½ in	1	1WDF4	4
Α	1 ½ in	1/2 in	2	1WDF5	2
Α	2 in	5⁄8 in	2	1WDF6	2

Key		w	Holes per Leaf	ltem No.	Pkg. Qty.
A	2 ½ in	3/5 in	2	1WDF7	4
A	3 in	3/4 in	2	1WDF8	4
	r Braces	7 1 111			
Zinc					
В	1 ½ in	3/4 in	2	1WDJ4	4
В	2 ½ in	3/4 in	3	1WDJ5	4
В	3 ½ in	3/4 in	3	1WDJ6	4
Double		Braces, Zir	1C		
С	1 ½ in	1 ½ in	3	1WDF1	1
С	2 in	1 ½ in	3	4PE75	1
C	2 ½ in	1 ½ in	3	4PE76	1
	orner Brad				
D	1 ½ in	3⁄8 in	2	4PE71	1
D	2 in	3⁄8 in	2	4PE72	1
D	2 ½ in	½ in	2 2	4PE73	1
D	3 in	31/64 in	2	4PE74	1
D	3 ½ in	3∕5 in	2 2 2	1WDK7	1
D	4 in	3/4 in	2	1WDK8	1
D	5 in	7∕8 in	2	1WDK9	1
D	6 in	1 in	3	1WDL1	1
Galvar					
D	3 in	½ in	2	1WDL3	4
D	4 in	5⁄8 in	2	1WDL4	4
	Braces				
Brass					
E	1 ¾ in	3/4 in	1	1WDL8	4
Zinc					
E	1 3/5 in	3/4 in	1	1WDL9	4
	ie Bronze				
Е	1 ¾ in	3/4 in	1	1WDN1	4

Key		w	Holes per Leaf	Item No.	Pkg. Qty.	
	ting Brace		110100 por 2001		w.y.	
F	2 ½ in	1 ½ in	6	1WDJ2	4	
Mendi	ing Plates		<u> </u>			
Zinc	•					
G	2 in	5⁄8 in	2	4PB67	1	
G	3 in	3/4 in	4	1WDG3	1	
G	4 in	⅓ in	4	4PB68	1	
G	5 in	1 in	4	1WDG4	1	
G	8 in	1 1/4 in	4	1WDG6	1	
G	12 in	1 1/8 in	6	1WDG8	1	
Galva	nized					
G	2 in	5⁄8 in	2 4	1WDG9	1	
G	4 in	⅓ in	4	1WDH2	1	
G	5 in	1 in	4	1WDH3	1	
Brass						
G	4 in	<sup>27</sup> / <sub>32</sub> in	4	1WDH9	4	
Tee Pl	ates, Zinc	;				
Н	2 ½ in	5% in	2 on Stem/3 on Top	4PB69	1	
H	3 in	3 in	2 on Stem/3 on Top	1WDK4	1	
Н	4 in	⅓ in	2 on Stem/3 on Top	1WDK5	1	
Н	5 in	5 in	2 on Stem/3 on Top	1WDK6	1	
Solid Brass Decorative Corner Braces						
	1 1/4 in	1 1/4 in	1	1XMP3	4	
	1 7/10 in	1 7/10 in	1	1XMP4	4	

1942